Photos of Painted Deteriorated Components
Date photos taken: 10/1/2019
Address: 8888 55th Street, Somewhere, Iowa 50841
Photos taken by: Joan Taylor

Dining wall paneling-west
Risk-nail holes chipped paint

kitchen wall plaster-south
Risk-walls scraped, paint dust

bathroom window-west
Risk-chipped woodwork

Door frame to upstairs-east
Risk-chipped woodwork

front door inside-north
Risk-chipped paint

bedroom window-north
Risk-chipped paint

Photos of Painted Deteriorated Components
Date photos taken: 10/1/2019
Address: 8888 55th Street, Somewhere, Iowa 50841
Photos taken by: Joan Taylor

Front of home faces north
Risk-chipped paint on slate siding

living room window-east
Risk-chipped paint on window casing

kitchen window-east
Risk-reduced -window replaced

Back of home "newer" addition kitchen and porch
Risk-if added after 1978 low risk

upstairs window - west
Risk-original to home chipping/peeling paint